

Illinois Commerce Commission
Pipeline Safety
Exit Meeting Documentation Form

Operator:	NORTHERN ILLINOIS GAS CO.
Inspection Unit(s):	NICOR - Crystal Lake, NICOR - Rockford
Date of Meeting:	10/31/2012
Pipeline Safety Analyst:	Charles Gribbins
Exit Meeting Contact:	Treves Williams

Issues Identified/Amendments/Probable Violations:

ISSUE(S) FOUND:

192.479(a) - Staff found a meter set at Cherry Vale Mall, meter number NG4287386, with possible disbonded coating. Staff also found some atmospheric corrosion issues with the following Pressure Regulating Stations; Linden Road & Mulford Road, Harrison Avenue & Ohio Parkway Street, Simpson Road & US Route 20. Staff advised the operator that the atmospheric corrosion issues need to be corrected.

ISSUE(S) CORRECTED:

NO ISSUES CORRECTED.

NOTICE OF AMENDMENT(S) FOUND:

NO NOAs FOUND.

NOA(S) CORRECTED:

NO NOAs CORRECTED.

NOTICE OF PROBABLE VIOLATION(S) FOUND:

NO NOPVs FOUND.

NOPV(S) CORRECTED:

NO NOPVs CORRECTED.

Pipeline Safety Analyst Signature:



Operator Representative Signature:

